

1983 Cessna Conquest II 441-0268 Dash 10 Engines



HIGHLIGHTS

Aircraft with Complete Logs & Records Since New
Garmin G600 / GTN750 / G5 Avionics Suite w/6-Screen EFIS
All SIDs Complete &Current
Honeywell Dash 10 Engines 645.1 /hour since OVH each
Four Blade Hartzell Propellers 126.5 /hour since OVH each



AIRFRAME

TOTAL TIME SINCE NEW	8,237.7
TOTAL LANDINGS SINCE NEW	7,960
ENTRY INTO SERVICE DATE	1983
CERTIFICATION DATE	January 21 th , 1982
HOME BASE	KTMB
PROGRAM COVERAGE	NA
MAINTENANCE TRACKING	NA
CERTIFICATION	Part 91

ENGINES

	Left Engine	Right Engine
DESCRIPTION	HONEYWELL TPE-331-10N-5155	HONEYWELL TPE-331-10N-5155
SERIAL NUMBER(S)	P-77418C	P-77197C
TOTAL HOURS SINCE NEW	5,248.2	4,995.5
TOTAL CYCLES SINCE NEW	4582	5194
TOTAL HOURS SINCE OVH	645.1	645.1
TOTAL CYCLES SINCE OVH	944	944

PROPELLERS

	Left	Right
DESCRIPTION	HARTZELL HC-E4N-5B/E8501K	HARTZELL HC-E4N-5B/E8501K
SERIAL NUMBER(S)	HE-263	HE-262
TOTAL HOURS SINCE NEW	2270.9	2270.9
TOTAL HOURS SINCE OVH	126.5	126.5



AVIONICS

Type of Unit	Quantity	Description
EFIS (Electronic Flight Instrument System)	Single (1) w Dual Screen	Garmin G600 PFD/MFD Display
FMS (Flight Management System) & GPS (Global	Dual (2)	Garmin GTN 750 WAAS GPS/Nav/Comm/MFD w/
Positioning System)		6.9" Touchscreen
ADC (Air Data Computer)	Dual (2)	Incorporated in Garmin G600
DME (Distance Measuring Equipment)	Dual (2)	Displayed in Garmin GTN750 / KN63
ADF (Automatic Direction Finder)	Single (1)	GDL 69/69A
ELT (Emergency Locator Transmitter)	Single (1)	Artex ELT-406
A/P (Autopilot)	Single (1)	Garmin GFC 600
WEATHER RADAR	Single (1)	Garmin GWX-70 Color Radar
RADAR ALT (Radar Altimeter)	Single (1)	Garmin GRA-55
PFD Standby Indicator Pilot Side	Single (1)	Garmin GI275 Standby
XPNDR (Transponder)	Dual (2)	Dual GarminGTX-33ES
ADS-B IN/OUT	Single (1)	Single GarminGDL-88 Receiver
Dual Copilot Side Instrumentation	Dual (2)	Garmin G5 - Primary Attitude Indicator & Heading Indicator (DG) & HSI for Certificated Aircraft

INTERIOR

INTERIOR	CONFIGURATION
Configuration	Beautiful eight-passenger executive interior configuration. Forward Four-placed Club upholstered in beige leather. Dual Executive Tables, Aft RH – Single Forward-Facing Seat in beige Leather. Rear Three Placed Divan in beige Leather. Blue carpet. Beige Runner.

EXTERIOR PAINT

Colors	Overall Color: Matterhorn White.
	Stripe Colors: Navy Blue & Sunfast Red
	Second Base Color: Horizon Blue.



CURRENT INSPECTION BEING PERFORMED

Location: Miami Executive Airport (KTMB). Maintenance facility: Propel Aviation Completion date of inspection: Aug 2023

- Pressurization Inspection & repair
- Supplemental Inspection Numbers:
- -27-10-05 Inspect aileron hinges, fittings, associated hardware, and components for condition.
- -32-10-05 Main Landing Gear Trunnion Inspection
- -32-10-06 Main Gear Shock Struts Visual Inspection
- -32-10-07 Main Landing Gear Trailing Link Inspection.
- -32-20-00 Nose Landing Gear Drag Brace Inspection/Replacement.
- -32-20-01 Nose Gear Attachment & Wheel Well Structure Inspection.
- -32-20-02 Nose Gear Fork Inspection.
- -32-30-08 Nose Gear Trunnion Inspection / Replacement.
- -32-50-00 Nose gear Steering Bell Crank Inspection.
- -52-10-02 Lower Cabin Door Hinges Inspection.
- -53-10-01 Horizontal & Vertical Stabilizer Attach Bulkheads.
- -53-10-02 Fuselage Left & Right-Hand Window Frame Stringers Inspection.
- -53-10-03 Inspection of the Forward Pressure Bulkhead at F.S. 100.00.
- -53-10-04 Inspection of the Aft Pressure Bulkhead at F.S. 324.94.
- -53-10-05 Inspection of the Aft Pressure Bulkhead at F.S. 324.94.
- -55-10-03 Horizontal Stabilizer Spars & Attachments Inspection.
- -55-10-04 Horizontal Stabilizer Forward Spar Upper Cap Inspection.
- -55-10-05 Horizontal Stabilizer Forward Spar Lower Cap Inspection.
- -55-10-06 Horizontal Stabilizer Front Spar Lower Cap near Attach Fitting Inspection.




CON'T CURRENT INSPECTION BEING PERFORMED

- -55-10-07 Horizontal Stabilizer Aft Spar Lower Cap Attach Inspection
- -55-10-08 Horizontal Stabilizer Aft Spar Lower Cap Inspection.
- -55-10-09 Horizontal Stabilizer Aft Upper Cap Inspection.
- -55-10-10 Horizontal Stabilizer Bond Inspection.
- -55-10-11 Horizontal Stabilizer Skin-to-Honeycomb Bond Inspection.
- -55-20-01 Outboard Elevator Hinge Bracket and Attachment Inspection.
- -55-20-02 Elevator Hinges & Fittings Inspection.
- -55-30-01 Vertical Stabilizer Spars & Attachments Inspection.
- -55-30-02 Rudder Hinges & Fittings Inspection.
- -55-30-03 Vertical Stabilizer Spar Attachments Inspection.
- -57-10-04 Front Spar Lower Cap from B.L 23.00 to C.W.S 30.00.
- -57-10-05 Aft Spar Lower Cap from B.L. 23.00 to C.W.S 112.10.
- -57-10-06 Main Spar Lower Wing Attach Fittings & Spar Cap at C.W.S 112.10
- -57-10-07 Center Wing Spar Web Inspection.









infosales@fenixaviation.com | +1 (305) 773-9525 / (305) 562-5171 | www.fenixaviation.com







